



Hamilton

Building Division

Reviewed for Ontario Building Code Compliance.

Subject to Corrections Noted on Plans and Field Inspections.


Permit: 21 104287 000 00 SS

Date: 05/19/21

Name: Laurie Smith

Approved by: *L. Smith*

Draft A, nov-20-2017-8pts



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

LL	PL	PI	Cc	Cu	D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay
			1.31	254.90	19	1.627	0.117	0.006	25.0	47.1		27.9

**Date:** Nov. 17 - 2020  
**Client:** Cedar Lane Bobcat Services  
**Contractor:**  
**Source:**  
**Sampled From:** TP 101  
**Sample No.:** 3  
**Date Sampled:** Nov. 12 - 2020  
**Sampled By:** RVD  
**Lab No.:** 1225  
**Date Tested:** Nov. 16 - 2020  
**Type of Material:** Gravelly Silty Sand, trace clay

Sieve Size (mm)	Percent Passing	No Specifications



CHUNG & VANDER DOELEN  
 ENGINEERING LTD.  
 311 Victoria Street North  
 Kitchener, Ontario N2H 5E1  
 Telephone: 519-742-8979  
 Fax: 519-742-7739  
 e-mail: info@cvdengineering.com

### GRAIN SIZE DISTRIBUTION

**Project:** Percolation Time Assessment  
**Location:** 688-690 Crooks Hollow Road, City of Hamilton  
**File No.:** W19212  
**Enclosure No.:** 3

DM - NO SPECIFICATIONS W19212 CEDAR LANE 688-690 CROOKS HOLLOW RD HAMILTON GPJ LAW LNDN GDT 20-11-17